ADDENDUM

CID 2903 Caller ID with Call Waiting
Cat. No. 43-2903

Page 13, the second sentence on the second bullet note incorrectly states “If this happens, remove the batteries, wait about 2 minutes (to reset the memory,) then start from Step 4.”

The correct instruction is, “If this happens, press and hold **REVIEW** ▲ and ▼ simultaneously until **SET AREA CODE** appears. Then reset the area code.”

Add the following to the table on Page 22, “Displayed Call Information.”

Display	Description
ERROR	Appears if the Caller ID information is garbled, or if there was an error during the transmission of Caller ID information.

© 2001 RadioShack Corporation. All Rights Reserved. RadioShack and RadioShack.com are trademarks used by RadioShack Corporation.

RadioShack Corporation
Fort Worth, Texas 76102

10A01 Printed in Malaysia